

## Department of Energy

Richland Operations Office P.O. Box 550 Richland, Washington 99352

00-OSS-317

MAY 5 2000

Mr. M. A. Wilson, Program Manager Nuclear Waste Program State of Washington Department of Ecology P.O. Box 47600 Olympia, Washington 98504

RECEIVED MAY 2 4 2000

**EDMC** 

Dear Mr. Wilson:

HANFORD FACILITY DANGEROUS WASTE PART A PERMIT APPLICATION, FORM 3, REVISION 6, FOR THE 241-Z TREATMENT AND STORAGE TANKS (241-Z) (TSD: T-2-5)

Enclosed is the Hanford Facility Dangerous Waste Part A Permit Application (Part A), Form 3, Revision 1, for the 241-Z. The 241-Z is located in the 200 West Area of the Hanford Facility.

The Part A, Form 3, Revision 6, has been revised to add Dangerous Waste Numbers D004 (arsenic), D006 (cadmium), and D010 (selenium). The U.S. Department of Energy, Richland Operations Office and Fluor Hanford, Inc. (FHI) Nuclear Material Stabilization Project will be initiating a stabilization process for the plutonium bearing solutions that will generate a large volume of mixed waste. This waste will be treated and stored in the 241-Z tank system. The addition of these dangerous waste numbers is required in accordance with Washington Administrative Code 173-303-805(7)(a).

If you have any questions regarding the Part A, Form 3, Revision 6, please contact Astrid Larsen, of my staff, on (509) 376-9333 or Jeff Bramson, of FHI, on (509) 373-1359.

Sincerely,

OSS:APL

Enclosure

cc w/encl:
EDMC, H6-08
Ecology Library, Kennewick
J. R. Wilkinson, CTUIR
L. E. Ruud, Ecology
A. B. Stone, Ecology

J. E. Bramson, FHI

J. F. Williams Jr., FHI
Environmental Portal, LMSI
P. Sobotta, NPT
R. Jim, YN

G. W. Jackson, FHI

R. H. Engelmann, FHI

fice of Site Services

isness, Director

### Enclosure

HANFORD FACILITY DANGEROUS WASTE PART A PERMIT APPLICATION,
FORM 3, REVISION 6
FOR THE
241-Z TREATMENT AND STORAGE TANKS (TSD: T-2-5)

				he unshad d for elite		only ., 12 charc	cter/inch	).												Rev. 6	6, 05/05/	00,	Pa	age	1 0	f 8	,
FO		Т			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, and arrest t			•			•								1. EPA/STATE I.D. NUMBER							
					D/	ANG	<b>iER</b>	ous	W/	<b>AST</b>	Έ	P	Ε	RI	Λľ	T A	<b>\PPLI</b>	CATION		W A 7 8 9 0 0 0 8 9 6 7					1		
FOR OFFICIAL USE ONLY										•												1					
APPLICATION DATE RECEIVED													COMMENTS														
APROVED (mo., day, & yr.)																							┨				
	<u></u>	_					<u> </u>																				
	_			SED AP			a. B 5.2	laus (====		nu set i	A =-	200.00				-4-1-	la sha #	naliantica var	ubonista - f	m. 10 da -1174		el e			. 14 44		4
is you	ur f	irst a	applica	ation an	d you a	already I	know yo	our facilit	y's EPA	STATE	Ë 1.C	D. Nu	ımt	er, c	or if t	tnis is	a revised a	oplication you are s oplication, enter yo	uomitting for y ur facility's EP	A/STATE	i.D. Numbe	r in s	Sect	ion l	abov	1(S / <del>()</del> .	
A. FI	RS				-			nd provid											. NEW FACII	ITY /Con	miete item i	helo	ו ע. ו ע		-	_	
	EXISTING FACILITY (See instructions for definition of "existing" facility.  Complete Item below.)											uity.									/						
	ſ	MC	$\dashv$ $\vdash$	DAY	YR.	FOR E	EXISTING	G FACILI EGAN O	TIES, PE R THE D	ROVIDE	TH-	HE DA	ATE JCT	(mo	., da	y, & y MMEN	r.) ICED	MC	DAY	YA. FO	R NEW FAC	DAT	ES, <u>E,</u>				l
		03	3][3	22	43	(use th	e boxee	to the lef	1)								,		_	ATI	OVIDE THE D., day, & yr.) ION BEGAN PECTED TO	OPI OR I	EFI- IS 2IN				
B. REVISED APPLICATION Splace an "X" below and complete Section ! above)																1											
								US PERM	AIT									<u> </u>	2. FACILITY H	AS A FINA	L PERMIT						╽
						CAPACIT		of nerve	es cortes	below	the	hee'	da	acrih	<b>M</b> A	ech or	ncess to he	used at the facility. 1	ien lines ere no	ovided for	entering and	ne 1	fmo	re lin	es er		$\frac{1}{2}$
ne	ed	ed, e	inter t	e codes (Section	(s) in ti	ne space	provide	d. If a pr	ocess wi	N be us	ed t	hat is	no	t incl	udec	in the	e list of code	s below, then describ	e the process (	(including i	ts design cap	acin	/) in	the a	pace	-	
•					-	V - For 4	each coc	je entered	d in colum	nn A er	nter	the c	ans	ecity (	of the	e nmc											
				Enter the				VINGI (F)		A DI			pe	I	., u A	_ pr.00											
						-	ount ent	ered in er	dumo B/:	1), ente	r th	e cori	e fr	rom ti	he lis	st of :=	nit measure :	codes below that des	cribes the unit	of measure	used.						
	Ö	inly t	he unit	s of me	asure II	net are li	sted belo	w should	be used	.,, <b></b> !.	•••		11		~ I#												
					_		PRO- CESS CODE	MEAS	ROPRIAT	R PRO	CE	OF SS								PRO- CESS	APPROPI MEASURI	E FO	RP	ROC	ESS		
-	tor	age:	P	ROCES	S		CODE	Di	ESIGN C	APACI	ΤY						₩.	PROCES	SS	CODE	DESIG	in C	APA	CIT	<u>r                                      </u>	-	
			NER (I	parrel, d	rum, eti	c.)	S01		NS OR L									WK		T01	GALLONS			Y OF	3		
l T	TANK S02 GALLONS OR LITERS WASTE PILE S03 CUBIC YARDS OR														JRFACE IMPOUND	MENT	LITERS PER DAY TO2 GALLONS PER DAY OR										
s	SURFACE IMPOUNDMENT S04 GALLONS OR LITERS												IN	CINERATOR	LITERS PER DAY TO3 TONS PER HOUR OR METRIC TONS PER HOUR;												
D	Disposal:																GALLONS PER HOUR OR LITERS PER HOUR										
ir L	VJE AN	ECTI IDFII	T ON M	ELL			D80 D81	ACRE-I	NS OR L	e volun	ne ti	hat					Ö	THER (Use for physi	cal, chemical,	, TO4 GALLONS PER DAY OR							
	would cover one acre to depth of one foot)													pi	ermal or biological tra ocesses not occurring reace impoundments	LITERS PER DAY											
ا إ	LAND APPLICATION D82 ACRES OR HECTARE-METER OCEAN DISPOSAL D83 GALLONS PER DAY OR							S						at	ors. Describe the pro e space provided: Se												
		URFACE IMPOUNDMENT D84 GALLONS OR LITERS													•												
							UNIT O	F									UNI	T OF SURE		UNIT OF							
				SURE			CODE					OF I					MEA CO	XDE	DF MEASURE CODE								
L	GALLONS							ON:	S PE RIC	R H	HOUF NS PI	} EA H	IOUR		D	HECTA ACRES	-FEETA ARE-METERF SB										
IŌ	CUBIC METERS GALLON								LON:	S PI	ен н	OUL	1	·····	E	HECAT	RES		•••••		*******	ā	ı				
					E)	CAMPLE	FOR CO	MPLETI	NG SEC	TION II	II (s	hown	in i	line n	umb	ers X	-1 and X-2 b	now): A facility has t	wo storage tan	ks; one ter	nk can				,		_
N	Т										gal	ions.	$\frac{n}{1}$	ne fac	HRY .	also h	1	nator that can burn up B.	to 20 galiona ( PROCESS DE		PACITY			Т		<del></del>	-
LV	ij	CE	PRO-		B. PROCESS DESIGN CAPACITY			1		JNIT	١,	FOR		LU	CESS						UN		FO OFFI		L		
NEE	1	CODE (from list					1. AMOUNT			SU		1	ŲSE	Ē	N B	(from list		1. AMOUN (specify)	т		8	URI	E	US	Ē	•	
F		ab	ove)				(specify)				(enter code)										(enter						
X-1	Ŧ	s	0 2	600				$\neg$	F	G	F	$\overline{\prod}$	T	5						1	Н		TI	T			
$\vdash$	$^{\dagger}$	╅	+								╅	┿	$\vdash$	H	+	╁	<del> </del>					+-	H	${}$	╅	+	-
X-2	+		0 3	<u> </u>		20				$\dashv$	+	Ε	H	₩	+	6	<u> </u>					+	Н	ert	┿	+	_
1	$\downarrow$	<u>S</u>	02	69,300						$\perp$	4	L	$\coprod$	1	7	ļ					$\bot$	$\sqcup$	$\sqcup$	44	+	_	
2			01			1	6,27	7			١	٧L				8	<u> </u>					$\perp$			$\coprod$		
3	T									$\neg$	1	T	Γ	П		9						Π		$\sqcap$	$\prod$		_
—	┿			<del></del>		-					+	+	٠	╆┉╂╴	+-	+	+	<del>                                     </del>				+	$\vdash$	<del>   </del>	┪┥	_	-

#### Continued from the front.

III, PROCESSES (continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS (code "TO4"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

#### S02

The 241-Z Treatment and Storage Tanks (241-Z) support the Plutonium Finishing Plant (PFP), which was constructed in November 1948. The 241-Z consists of storage tanks D-4, D-5, D-7, D-8, and an overflow tank. Tanks D-5 and D-8 also serve as the waste treatment tanks. These tanks, located in the belowground portion of the 241-Z Building, have a combined storage capacity of 69,300 liters (18,307 gallons). Tanks D-4 and D-5 each have a capacity of 16,400 liters (4,332 gallons), while tanks D-7 and D-8 each have a capacity of 17,900 liters (4,729 gallons). The overflow tank, located in the D-7 Vault, has a capacity of 700 liters (185 gallons) and is in place to serve only in a capacity for receiving waste that might overflow from one of the other tanks. The overflow tank is not in place to serve as storage capacity for dangerous waste. The 241-Z accumulates and stores mixed waste generated from PFP process activities. Once treated, the waste is stored before final transfer to the Double-Shell Tank (DST) System. The original construction of 241-Z included a fifth 16,400-liter (4,332-gallon) tank that also is located in the belowground portion of the facility. Tank D-6 was taken out of service and isolated from the 241-Z tank system in 1972 and never stored dangerous waste. The purpose of identifying tank D-6 is to note its existence within the 241-Z Building, but not to include it with the tank system covered by the Part A, Form 3, for the 241-Z. The maximum process design capacity for tank storage is 69,300 liters (18,307 gallons).

#### T01

Treatment that occurs in tanks D-5 and D-8 consists of a batch process that includes the addition of sodium hydroxide or potassium hydroxide, sodium nitrite, ferric nitrate, and water. The sodium hydroxide is added to adjust the pH of the waste to make the waste more amenable for transfer to the DST System. Ferric nitrate solution is added to provide 1 percent stable solids for transfer to the DST System, while water could be used to adjust the plutonium concentration of the waste to be transferred so that the waste meets the DST System criteria for acceptance. This treatment process makes the waste more amenable for transfer to the DST System. The maximum process design capacity for tank treatment is 16,277 liters per day (4,300 gallons per day).

#### IV. DESCRIPTION OF DANGEROUS WASTES

- A. DANGEROUS WASTE NUMBER Enter the four digit number from Chapter 173-303 WAC for each listed dangerous waste you will handle. If you handle dangerous wastes which are not listed in Chapter 173-303 WAC, enter the four digit number(s) that describes the characteristics and/or the toxic contaminants of those dangerous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	P	KILOGRAMS	K
TONS	T	METRIC TONS	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

#### D. PROCESSES

#### 1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed dangerous wastes: For each characteristic or toxic contaminant entered in Column A, select the code(s) from the list of process codes contained in Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed dangerous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER - Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

- Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. In column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "Included with above" and make no other entries on that line.
- Repeat step 2 for each other Dangerous Waste Number that can be used to describe the dangerous waste.

EXAMPLE FOR COMPLETING SECTION IV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a

	Τ		Α.					C. UNIT		D. PROCESSES											
BZ-ZE		DANGEROUS WASTE NO. (enter code)			D.	B. ESTIMATED ANNUAL QUANTITY OF WASTE		OF MEA- SURE (enter code)			1. PROCESS CODES (enter)										2. PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	, ,	Ķ	0	5	4	900		P		r	0	3	D	8	0		Ţ				
X-2	2 1	7	0	0	2	400		P		7	0	3	D	8	0		Τ	Τ			
X-3	3 1	,	0	0	1	100		P		7	0	3	D	8	0		Ī		П		
х-		7	0	0	2					r	0	3	D	8	0			Τ	П		included with above

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list. 1. D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE A. DANGEROUS WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES 2. PROCESS DESCRIPTION (enter (enter) (if a code is not entered in D(1)) E (enter code) code) Κ Treatment - Tank D002 1,360,777 T01 1 D004 2 D005 3 D006 D007 5 D008 6 D009 D010 8 D011 D019 10 **WT01** 11 WT02 Included with above. 12 Κ **S02** D002 2,494,758 Storage - Tank 13 D004 14 D005 D006 16 D007 17 D008 18 D009 19 D010 20 D011 21 D019 22 **WT01** 23 **WT02** Included with above. 24 25 26 ECY 030-31 Form 3 CONTINUE ON REVERSE ECL - 30 - 271 -Page 3 of 8

Continued from the front,		<del></del>				
IV. DESCRIPTION OF DANGEROUS WASTE (continued)			<del></del> _			
E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES	FROM SECTION D(1) ON PAGE	3.				•
The waste received by the 241-Z find dangerous waste numbers as deteived Waste could designate corrosive (I chromium (D007), lead (D008), medical Depending on the waste stream re (WT01 or WT02).	rmined through proces D002), and/or toxic for ercury (D009), seleniur	is knowledge, modelin arsenic (D004), bariun n (D010), silver (D011)	g, and som n (D005), c ), or carbon	e pro admid tetra	cess sampling. um (D006), chloride (D019).	• .
					•	
		•				
		•				
		•				
		•	•			
					• -	
		•	•			
<b>\</b>	•					
·						
V. FACILITY DRAWING Refer to attached drawing(s).	<del></del>		·			-
All existing facilities must include in the space provided on page 5	a scale drawing of the facility (see	instructions for more detail).		-		<del></del>
VI. PHOTOGRAPHS Refer to attached photograph(s).						
All existing facilities must include photographs (serial or ground-le treatment or disposal areas (see instructions for more detail).	evel) that clearly delineate all existi	ng structures; existing storage, trea	stment and dispo	sai area	s; and sites of future store	age,
	nis information is provided	on the attached drawings a	and photos			-
LATITUDE (degrees, minutes, & sec	· · · · · · · · · · · · · · · · · · ·		TUDE (degrees,	minutes	& seconds)	<del></del>
			111	11	,	
			L	<u> </u>		
VIII. FACILITY OWNER			<del></del>	11		
						<del>~</del>
A. If the facility owner is also the facility operator as listed in     B. If the facility owner is not the facility operator as listed in:			to the left and sk	dp to Se	ction XI below.	
				·····		
1. NAM	E OF FACILITY'S LEGAL OWNER	<u>(                                    </u>			2. PHONE NO. (eree	code & no.)
				Ī		
	<del></del>			$\rightrightarrows$		
3. STREET OR P.O. BOX		4. CITY OR TOWN		5. ST.	6. ZIP COD	E .
· ·			1			İ
						<u> </u>
IX. OWNER CERTIFICATION			_		<u> </u>	
I cartify under penalty of law that I have personally examined and immediately responsible for obtaining the information, I believe th information, including the possibility of fine and imprisonment.	am familiar with the information so at the submitted information is true	ibmitted in tifs and all attached do , accurate and complete. I am av	cuments, and tha vere that there an	t based a signific	on my inquiry of those in ant penalties for submitti	dividuals ng false
NAME (print or type)	SIGNATURE /	,	l	DATE S	GNED	
Keith A. Klein, Manager		///		-1	•	
U.S. Department of Energy	\		Į.	5/4	7/W	
Richland Operations Office	1///// 14	.000			·	
X. OPERATOR CERTIFICATION	U		,			
It certify under penalty of law that I have personally exemined and immediately responsible for obtaining the information, I believe th information, including the possibility of fine and imprisonment.						
NAME (print or type)	SIGNATURE		<u> </u>	DATE S	IGNED *	
SEE ATTACHMENT	}		j.	H Q		
ECL30 - 271	 	4 of 8			CONTINUE OF	DAGES
E01 000-01 (OIII 0	rage	7 101 10			COM HADE OF	4 LVAC 3

#### X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

Owner/Operator
Keith A. Klein, Manager
U.S. Department of Energy

U.S. Department of Energy Richland Operations Office

4-10-00

Ron D. Hanson

President and Chief Executive Officer

Fluor Hanford

Date


Date

## 241-Z Treatment and Storage Tanks 000 000 0000 0000 \_244-TX 231-Z 19th Street **Hanford Site** Dayton Avenue \_TSD Boundary 46\* 32' 55" 200 East Plutonium 241-Z Finishing Tanks Plant Tanks Complex 119° 38' 20" 100 Feet 500 H96070161.5


30 Meters

E

## 241-Z Building Cutaway View



# **241-Z BUILDING**



46°32'58" 119°38'20"

8706219-5CN (PHOTO TAKEN 1987)

### HANFORD FACILITY DANGEROUS WASTE PART A PERMIT APPLICATION, FORM 3, FOR THE 241-Z TREATMENT AND STORAGE TANKS (241-Z)

This portion of the Hanford Facility Dangerous Waste Part A permit application (Part A) consists of Form 3, Revision 6, that describes the 241-Z unit in general terms.

The 241-Z Part A, Form 3, has been revised to add Dangerous Waste Numbers D004 (arsenic), D006 (cadmium), and D010 (selenium). The Nuclear Materials Stabilization Project will be initiating a stabilization process for the plutonium bearing solutions that will generate a large volume of mixed waste. This waste will be treated and stored in the 241-Z tank system. The addition of this dangerous waste number is required in accordance with Washington Administrative Code 173-303-805(7)(a).

The following is an overview of the contents of the 241-Z Part A, Form 3:

Section I <u>U.S. Environmental Protection Agency/State Identification Number</u> – No change.

Section II <u>First or Revised Application</u> – No change.

Section III Processes - Codes and Design Capacities - No change.

Section IV

Description of Dangerous Waste - This section describes the waste that is treated and stored at 241-Z. In Block A, for Process Design Codes "T01" (Treatment - Tank) and "S02" (Storage - Tank) add Dangerous Waste Numbers D004, D006, and D010. Block B, no change. Block C, no change. Block D.1, no change. Block D.2, no change. Section IV.E, Description of Dangerous Waste add D004, D006, and D010 to text.

Section V Facility Drawings - No change.

Section VI <u>Photographs</u> - No change.

Section VII <u>Facility Geographic Location</u> - No change.

Section VIII <u>Facility Owner</u> - No change.

Section IX Owner Certification - The certification is signed by the Manager, U.S. Department of Energy, Richland Operations Office (RL).

Section X Operator Certification - An attachment is provided with Form 3 to be signed by the Manager, RL, as Owner/Operator and a corporate officer of Fluor Hanford, Inc. as Co-operator. These signatures certify management's belief that the submitted information is true, accurate, and complete.